








SPLIT SYSTEM SERVICE PACKAGES








\$199

STANDARD

-  20-point service
-  Clean filters + outdoor coils
-  Check refrigerant levels + leaks
-  Test unit operation
-  Inspect insulation + louvres
-  Indoor temp check
-  Service report





\$269

PREMIUM

-  20-point service
-  Clean filters + outdoor coils
-  Check refrigerant levels + leaks
-  Test unit operation
-  Inspect insulation + louvres
-  Indoor temp check
-  Service report
-  Remove + deep clean internal parts
-  Seal wall penetrations

\$359

PLATINUM

-  20-point service
-  Clean filters + outdoor coils
-  Check refrigerant levels + leaks
-  Test unit operation
-  Inspect insulation + louvres
-  Indoor temp check
-  Service report
-  Remove + deep clean internal parts
-  Seal wall penetrations
-  Replace remote batteries
-  Priority service
-  Summer breakdown guarantee
-  15% off spare parts

TONKIN

Prices include GST. Travel charges may apply if outside designated postcodes (2640, 2641, 3690, 3691). Additional diagnostic work may incur a fee.